



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization		Mandatory Information Required	
Company Name		Esso Exploration and Production Nigeria Limited -EENL	
Reporting Officer		Niyi Ogunmolu	
Designation		Erha Asset Manager	
Phone Number		+2349087627301	
Email Address		omoniyi.ogunmolu@exxonmobil.com	
Incident Number		001/2026	
Section 2 - Location			
State / LGA		Erha FPSO OML 133 / Offshore	
Coordinates of spill		EASTINGS 5Deg 21Min/4Secs N NORTHINGS 4Deg 20Min/5Secs E	
		☐ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☒ Offshore ☐ Subsea ☐ Swamp Area ☐ Others	
Depth of Water (if applicable)			
Section 3 – Spill Details			
Date and Time of spill		1/16/2026 Time: 17:20 hours local time	
Source of spill – Facility		TRANSPORTATION FACILITIES ☐ Ocean Tanker /Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☐ Pipeline PIPELINE (Specify pipeline diameter) ☐ Trunkline ☐ Flowline ☐ Bulkline ☐ Export line ☐ Gas Line STORAGE TANKS ☐ Underground Storage Tanks ☐ Above-Ground Storage Tanks ☐ Others (specify)..... PRODUCTION FACILITIES ☐ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☒ FPSO ☐ Refinery ☐ Others.....	
Cause of spill		Equipment Failure: A silvery sheen was observed in the vicinity of the Single Buoy Mooring (SBM) during export operations. The sheen did not originate from the SBM itself and is suspected to have resulted from a leaking hose.	
Status of spill		☒ Contained ☐ Not Contained ☐ Unknown	
Containment Measures in Place		☐ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☐ Sorbent ☒ Others (Suspected leaking hose isolated and sheen stopped; sheen observed to self-dissipate and sea state cleared)	
Product Data	☐ Persistent		☒ Non Persistent
	Product Name/Type		
	SG/API Gravity		
	Pour Point		
	Wax Content		
	Sulphur Content		

	Viscosity		
Oil	Slick Locations(s)		
observ ation	Slick Dimension(s)		
	Orientation of slick(s)		
	Distribution of oil		
	Obvious odour		
Oil descrip tions	Tarballs (tb)		
	Convergence line (co)		
	No structure (ns)		
	Windrows (wr)		
	Streamers (st)		
	Patches (pa)		
Oil color and appear ance	Silver/grey		X
	Rainbow		
	Metallic		
	Transitional		
	Dark		
Surveillance Method		☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☐ Boat ☐ On site ☒ Others (Surveillance from field personnel)	
Section 4 – Approximate Duration			
Releas e Rate	Instantaneous Release		Continuous Release
		Per Hour	☐ Hours ☐ Days
Descrip tion of observ ed spill	Estimated Quantity (bbl)	About 0.002642 of Oily Water based on sheen appearance	
	Coverage		
	Direction of travel		
Section 5 - Weather			
METEOROLOGICAL DATA			NIMET weather forecast
Wind Direction (wind direction given from)		North West	
Initial Wind Speed		4.2 knts	
Air Temperature (C or OF)		27 deg C	
Visibility Estimate		☒ Good ☐ Fair ☐ Poor	
OCEANOGRAPHIC DATA			
Water Current Speed			
Tide Phase: Flood		High ☐ Ebb ☐	
Water Temperature (OC or OF)		25 deg C	
High Tide Time			
Source			
Section 6 – Pre-Entry Activities			NOT APPLICABLE
Mechanical cleaning		Yes ☐ No ☐	
Recovery of free phase oil		Yes ☐ No ☐	
Booming		Yes ☐ No ☐	
Wild life rehabilitation		Yes ☐ No ☐	
Dispersant application		Yes ☐ No ☐	
Section 7 – Pre-Entry Activities			NOT APPLICABLE
Spill Trajectory Modeling		Surface 2D ☐ Sub-Surface 3D ☐	Not at this time ☐

Section 8– Equipment

On Site

DS

DS

REPORTING OFFICER: Niyi Ogunmolu

DESIGNATION: for: Erha Asset Manager

Signed by:

Niyi Ogunmolu

SIGNATURE:03DB2925592E4A.....

January 19, 2026

DATE:

**RBA Report must be submitted within 24 Hours of the Spill Incidence.*