

INCIDENT NUMBER: 5354-FEP-SAFM-00002



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: FIRST EXPLORATION AND PETROLEUM DEVELOPMENT COMPANY LIMITED

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify)

3. Incident Details

- i. Date of Incident: FEBRUARY 4TH, 2026 ii. Date first reported: FEBRUARY 5TH, 2026
iii. Date of first investigation: FEBRUARY 11TH, 2026
iv. Date of follow-up investigation:
v. Time investigation started: 11:20 HRS
vi. Estimated quantity spilled: NO TRACE OF CRUDE OIL AS AT THE TIME OF JIV.

4. Site Details

- i. Site/Location: ABIGAIL JOSEPH FPSO
ii. Position of Spill/Leak: N3° 52' 12.7085 E 5° 52' 12.8085

iii. Spill area

- ☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (Specify)

iv. Structural Controls in Place

- ☒ Boom ☒ Trenches ☒ Bund Wall ☒ Sorbents ☒ Others (Specify) N/A

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock N/A

ii. Type of Oil Contaminant

- ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (Specify)

iii. Facility

- ☒ Pipeline ☒ Flow Line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant
☒ Others (Specify)

iv. Cause of Spill

- ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (Specify) ACT OF NATURE (SQUALL)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (Specify) NONE

6. Impact of Incident

i. Properties Impacted by the incident

- ☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water
☒ Venerable Objects ☒ Others (Specify)

ii. Nature of impact

- ☒ Oil stained vegetation ☒ Oil stained fishing nets ☐ Dead floating fishes
☒ Dead floating crabs ☒ Withering of vegetation ☒ Others (Specify) .. NONE

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

- i. N/A
 ii.
 iii.
 iv.

(b) Land (Indicate area in m²)

- i. N/A
 ii.
 iii.
 iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken..... N/A

10. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

11. Remarks/Recommendation... FIRST F&P SHOULD EXPEDITE ACTION IN COMPLETING THE ONGOING LAYING OF ABOUT 1.7km PIPELINE AWAY FROM THE PLATFORM TO AVOID FUTURE OCCURRENCE OF SIMILAR SITUATION

12. Time Investigation ended 12:00 HRS

13. Name and Signature of Participants

❖ NOSDRA

1. UKPENEVI E. SOLOMON [Signature] 11/02/2026
2. Ezeamaechi Eji ofor C [Signature] 11/02/2026
3.

❖ NUPRC/NMDPRA

1. Chigorom Mwanimo [Signature] 11/02/2026
2. Abdullahi Abubakar / NUIMS [Signature] 11/02/2026
3.

❖ STATE MINISTRY OF ENVIRONMENT

1. Pozo Jaramuno [Signature] 11/02/2026
2.
3.

❖ LOCAL GOVERNMENT COUNCIL

1.
2.
3.

❖ COMPANY

1. Tosin Amida [Signature] 11/2/2026
2. Dominic Subi [Signature] 11/2/26
3.

❖ COMMUNITY

1.
2.
3.