



PICTURES TAKEN AT SITE:



SPILL POINT BEFORE EXCAVATION



SPILL POINT AFTER EXCAVATION



REPAIR WORK DONE BY NAOC REPAIR TEAM