

APPENDIX A

PHOTOGRAPHS TAKEN DURING INSPECTION VISIT

SPILL POINT BEFORE EXCAVATION



SPILL POINT AFTER ECAVATION



DISCONNECTION OF INSTALLED VALVE POINT SHOWN

