

APPENDIX A



On arrival at the incident point



Incident point with 2" Valve with pipe Connection Installed.



Repaired incident point

APPENDIX A



On arrival at the incident point



Incident point with 2" Valve with pipe Connection Installed.



Repaired incident point