



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NAOC [2014/SAR/038/057]

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify) CRUDE OIL

3. Incident Details

- i. Date of Incident: 18/01/14 ii. Date first reported: 18/01/14
iii. Date of first investigation: 18/01/14
iv. Date of follow-up investigation:
v. Time investigation started: 09:31 HRS
vi. Estimated quantity spilled: 3 LITRES

4. Site Details

- i. Site/Location: 18" TERBIDABA/BRASS PIPELINE AT KAMBORO (2)
ii. Position of Spill/Leak: N 04° 32' 51.5" E 005° 56' 28.5"

iii. Spill area

- ☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 0'Clock ☒ 10 0'Clock ☒ 2 0'Clock ☒ 3 0'Clock
☒ 4 0'Clock ☒ 5 0'Clock ☒ 6 0'Clock

ii. Type of Oil Contaminant

- ☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
☐ Others (Specify)

6. Impact of Incident

i Properties impacted by the incident

☐Farmland ☐Fish Pond ☐Vegetation ☐Fishing Net ☐Surface water

☐Venerable Objects ☐Others (specify).....

ii. Nature of impact

☐Oil stained vegetation ☐Oil stained fishing nets ☐Dead floating fishes

☐Dead floating crabs ☐Withering of vegetation ☐Others.....

iii. Delineation of impacted area

☒Within Company's facility/ROW ☐Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

i.

ii.

iii.

iv.

b) Land (indicate area in m²)

i.

ii.

iii.

iv.

b) Creeks/Creek lets

☐Tidal

☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐Tidal

☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐Tidal

☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. **Photograph/Map/Chart Ref.**

☒ Still photographs ☐ Video coverage ☐ Mapping

9. **Samples taken**.....

10. **Investigation carried out by**

☐ Foot ☒ Boat ☐ Aircraft

11. **Remarks/Recommendation**.....

..... JIV/REPAIRS WAS COMPLETED
..... INCREASE IN SURVEILLANCE
.....