



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: SPDC

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)

3. Incident Details

- i. Date of Incident: 5-03-2014 ii. Date first reported: 5-03-2014
iii. Date of first investigation: 6-03-2014
iv. Date of follow-up investigation: 7th & 8th of March, 2014
v. Time investigation started:
vi. Estimated quantity spilled: 16 barrels

4. Site Details

- i. Site/Location: 24th NKPOKU - BOMU TRANS NIGER P/L
ii. Position of Spill/Leak: PTA: 04° 41' 42.6" E 007° 16' 43.2"
iii. Spill area: PTB 04° 41' 42.6" E 007° 16' 43.1"

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☒ Others (Specify) Containment Pit

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 0'Clock ☐ 10 0'Clock ☐ 2 0'Clock ☐ 3 0'Clock
☐ 4 0'Clock ☐ 5 0'Clock ☐ 6 0'Clock

PT-A at 12 0'Clock
PT-B at 9 0'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (Specify)

6. Impact of Incident

i. Properties Impacted by the incident

- ☒ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify)

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify)

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

(b) Land (Indicate area in m²)

- i. BIARA i. 0-0345
 ii. ii.
 iii. iii.
 iv. iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>NOT</u>	<u>APPLICABLE</u>		

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>NOT</u>	<u>APPLICABLE</u>		

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>NOT</u>	<u>APPLICABLE</u>		

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>NOT</u>	<u>APPLICABLE</u>		

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation..... SPDC should clean-up the
impacted area and also improve its
surveillance on its facility.

12. Time Investigation ended.....

13. Name and Signature of Participants