

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NAOC
2. Type of Complaint/Incident: INCIDENT NO. 2014/SAR/229/316
- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
- ☐ Others (Specify)

3. Incident Details

- i. Date of Incident: 13/4/14 ii. Date first reported:
- iii. Date of first investigation: 13/4/14
- iv. Date of follow-up investigation:
- v. Time investigation started: 1127 HRS
- vi. Estimated quantity spilled: NIL

4. Site Details

- i. Site/Location: 18" TEBIDABA/BRASS PIPELINE AT LAGOS GBR
- ii. Position of Spill/Leak: N04° 27' 29.4" E006° 10' 26.0" (7)

iii. Spill area

- ☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
- ☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
- ☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
- ☐ Others (Specify)

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
- ☐ Storage Tank ☐ Compressor Plant
- ☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
- ☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
- ☒ Others (Specify) UNKNOWN PERSON(S) INSTALLED 3" VALVE WITH HOSE CONNECTION ON THE FACILITY FOR OIL THEFT ACTIVITY.

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify)

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify)

iii. Delineation of Impacted area

- ☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

(b) Land (Indicate area in m²)

- i. i.
 ii. ii.
 iii. iii.
 iv. iv.

(c) Creek/Creek lets ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
NOT APPLICABLE			

(d) Swamp ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
NOT APPLICABLE			

(e) River ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
NOT APPLICABLE			

(f) Shoreline/water ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
NOT APPLICABLE			

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot ☒ Boat ☐ Aircraft

11. Remarks/Recommendation.....

SIV AND REPAIRS WERE COMPLETED. CLEAN
UP IS NOT REQUIRED.

12. Time Investigation ended.... 1300 HRS.....