

ID: 2097259

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: SHELL PETROLEUM DEVELOPMENT COMPANY (SPDC)

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)

3. Incident Details

- i. Date of Incident: 08 JUNE, 2018 ii. Date first reported: 11 JUNE, 2018
iii. Date of first investigation: 12 JUNE, 2018
iv. Date of follow-up investigation: NOT APPLICABLE
v. Time investigation started: 12:15 HRS
vi. Estimated quantity spilled: 0.3 BBL(S)

4. Site Details

- i. Site/Location: UBLE WELL 5 HS WELL HEAD @ ISU-EKPEYO
ii. Position of Spill/Leak: N 05° 6' 44.42" E 006° 33' 3.92"
iii. Spill area
☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☒ Others (Specify) CELLAR PIT

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

NOT APPLICABLE

- ☐ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)

iii. Facility

- ☐ Pipeline ☐ Flow Line ☒ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☐ Checkered Mark ☐ Drilled Hole ☐ Blasting ☐ Theft ☐ Acid

6. Impact of Incident

i. Properties Impacted by the incident

☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water

☐ Venerable Objects

☐ Others (Specify)

SPILL CONTAINED WITHIN THE
ENGINEERED SURROUNDING OF
THE WELL HEAD

ii. Nature of impact

☐ Oil stained vegetation

☐ Oil stained fishing nets

☐ Dead floating fishes

☐ Dead floating crabs

☐ Withering of vegetation

☐ Others (Specify)

iii. Delineation of Impacted area

☒ Within Company's facility/ROW

☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate none)

i. IDU - ERPEYE

ii.

iii.

iv.

(b) Land (Indicate area in m²)

i. 44.17m²

ii.

iii.

iv.

(c) Creek/Creeklets

☐ Tidal

☐ Non tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
NOT	APPLICABLE		

(d) Swamp

☐ Tidal

☐ Non tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
NOT	APPLICABLE		

(e) River

☐ Tidal

☐ Non tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
NOT	APPLICABLE		

(f) Shoreline/water

☐ Tidal

☐ Non tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
NOT	APPLICABLE		

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... **NONE TAKEN**

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation **Unknown Person tampered with the valves on UBLE Well 5 L/S and caused oil spill from the well head. It is recommended that the Cellar Pot be evacuated.**

12. Time Investigation ended... **14:03 HRS**