

Spill ID: ~~61647-635679~~

ID: 128397

87

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: PDMC ABASI

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)

3. Incident Details

- i. Date of Incident: 05/07/17 ii. Date first reported:
iii. Date of first investigation: 10/07/2017
iv. Date of follow-up investigation:
v. Time investigation started: 12:57 PM
vi. Estimated quantity spilled: Non

4. Site Details

- i. Site/Location: Km 64.8 GADABIYU NITEL MAST
ii. Position of Spill/Leak: N 08° 34' 01" E 006° 55' 057"

iii. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☐ Crude Oil ☒ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☒ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (Specify)

Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland
- ☐ Fish Pond
- ☐ Vegetation
- ☐ Fishing Net
- ☐ Surface water
- ☐ Venerable Objects
- ☐ Others (Specify)

ii. Nature of impact

- ☐ Oil stained vegetation
- ☐ Oil stained fishing nets
- ☐ Dead floating fishes
- ☐ Dead floating crabs
- ☐ Withering of vegetation
- ☐ Others (Specify)

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW
- ☐ Outside Company's facility/ROW

Extent of Impact

- a) Community (Indicate name)

i.

ii.

iii.

iv.
- (b) Land (Indicate area in m²)

i.

ii.

iii.

iv.

- (c) Creek/Creek lets
- ☐ Tidal
- ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

- (d) Swamp
- ☐ Tidal
- ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

- (e) River
- ☐ Tidal
- ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

- (f) Shoreline/water
- ☐ Tidal
- ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation.....

12. Time Investigation ended.....

13. Name and Signature of Participants

❖ NOSDRA

1. Yakub ~~Abasi~~ ~~NOSDRA~~ ~~Signature~~ 10/07/17
2. Abel Emmanuel Yashim NOSDRA ~~Signature~~ 10/7/2017
3. Aminu Muhammed NOSDRA ~~Signature~~ 10/7/2017
- ❖ DPR 4. MUHAMMAD SULEIMAN ~~Signature~~ 10/7/2017

1.
2.
3.

❖ STATE MINISTRY OF ENVIRONMENT

1.
2.
3.

❖ LOCAL GOVERNMENT COUNCIL

1.
2.
3.

❖ COMPANY

1. NNPC (PPMC) ~~Signature~~ Pump Station. 10/07/2017
2.
3.

❖ COMMUNITY

1.
2.
3.