



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGER DELTA PETROLEUM RESOURCES LTD.

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....

3. Incident Details

i. Date of Incident: 20-07-2018 ii. Date first reported: 24-07-2018

iii. Date of first investigation: 25-07-2018

iv. Date of follow-up investigation:.....

v. Time investigation started: 11:40 hrs

vi. Estimated quantity spilled: 5.4 bbls (RECOVERED 5.0 BBLs)

4. Site Details

i. Site/Location: 6" OGBELE FLOWLINE ROW AT OGBELE

ii. Position of Spill/Leak: BOTTOM OF FLOWLINE (NO240020)
E 0544148

iii. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....

iv. Structural Controls in Place

- ☒ Boom ☐ Trenches ☐ Bund wall ☒ Sorbents ☐ Others (specify).....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☒ 6 O' Clock

ii. Type of Oil contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify).....

iii. Facility

- ☐ Pipeline ☒ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....

iv. Cause Of Spill

- ☐ Corrosion ☒ Equipment Failure ☐ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify).....

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify)..... NIL

6. Impact of Incident

i Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☒ Surface water
☐ Venerable Objects ☐ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☒ Withering of vegetation ☒ Others. *OIL SLICK ON WATER*

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

- i. *OGBELE*
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i. *250m x 17m = 4250m²*
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☒ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation 1.) COMMENCE IMMEDIATE CLEAN-UP
OF IMPACTED AREA WITH SITE MONITORING BY THE AGENCY.
2.) STEP-UP SURVEILLANCE OF FLOWLINE ROW TO ENSURE
THERE ARE NO OTHER LEAK POINTS.

12. Time investigation ended 15:30 HRS