



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY (NAOC)
2. Type of Complaint/Incident:
☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify).....
3. Incident Details
 - i. Date of Incident: 04/02/2019 ii. Date first reported: 04/02/2019
 - iii. Date of first investigation: 04/02/2019 iv. Spill Incident No: 2019/SAR/017
 - v. Date of follow-up investigation: 06/02/2019
 - vi. Time investigation started: 11:30
 - vii. Estimated quantity spilled(bbls): 8 BBLs viii. Quantity Recovered: NIL
4. Site Details
 - i. Site/Location: 24" OGODA/BRASS PIPELINE AT ATONYEKIRI
 - ii. State: BAYELSA iii. L.G.A.: BRASS NEMBE LGA
 - iv. Spill Co-Ordinates: N(m) N04° 26' 30.2"
E(m) E006° 21' 18.9"
 - v. Spill area
☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☐ Offshore ☒ Others (specify).....
 - iv. Structural Controls in Place
☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify).....
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock
 - ii. Type of Oil contaminant
☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (specify)
 - iii. Facility
☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☐ Rig
☒ Storage Tank ☒ Compressor Plant ☒ Others (specify).....
 - iv. Cause of Spill
☐ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (specify).....
 - v. Visible Sign of Third Party Interference
☒ Jacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (specify).....



6. Impact of Incident

i. Properties impacted by the incident

- ☒ Farmland ☐ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water
☒ Venerable Objects ☐ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes
☒ Dead floating crabs ☒ Withering of vegetation ☒ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops ☒ Fish Farm/ Pond ☒ Fishing Net ☒ Makeshift
☒ Permanent ☒ Others

8. Extent of Impact

a) Community (indicate name)

- i.
 ii.
 iii.
 iv.

b) Land (indicate area in m^2)

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☐ Mapping

10. Samples taken.....

11. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

12. Remarks/Recommendation IMPACTED AREA SHOULD BE CLEANED
UP AS SOON AS POSSIBLE.

13. Time investigation ended.....