

PICTURE TAKEN AT SITE



PIC 1. Before Excavation



Pic 2. Installed 3" Valve



Pic 3. Repair work