

7.0 PHOTOGRAPHS TAKEN:



A
FIG A: Note dropped by vandals along ROW



B
FIG B: Incident point on arrival



C
FIG C: Incident point on exposure



D
FIG D: Incident point after repairs