



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AIRCRAFT OIL COMPANY (NAOC)
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....
3. Incident Details
i. Date of Incident: 20/01/19 ii. Date first reported: 20/01/19
iii. Date of first investigation: 21/01/19 iv. Spill Incident No: 2019/SAR/006
v. Date of follow-up investigation: —/—/—
vi. Time investigation started: 11:00 HRS
vii. Estimated quantity spilled(bbls): 104 viii. Quantity Recovered: 0-25 bbls
4. Site Details
i. Site/Location: 10th CLOUGH CREEK / TEBOMBA PL D APOI
ii. State: BAYELSA iii. L.G.A: SOUTHERN LGAN
iv. Spill Co-Ordinates: N(m) 04° 43' 54.6"
E(m) 005° 50' 59.3"
v. Spill area
☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....
- iv. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☒ 12 O' Clock ☐ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
- ii. Type of Oil contaminant
☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify)
- iii. Facility
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....
- iv. Cause of Spill
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify).....
- v. Visible Sign of Third Party Interference
☒ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify) ABOUT 170 MM HACK SAW CUT
FROM 12 O'CLOCK TO 3 O'CLOCK POSITION.



6. Impact of Incident

i. Properties impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
☒ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation
☒ Oil stained fishing nets
☒ Dead floating fishes
☒ Dead floating crabs
☒ Withering of vegetation
☒ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW
☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops
☒ Fish Farm/ Pond
☒ Fishing Net
☐ Makeshift
☒ Permanent
☒ Others

8. Extent of Impact

a) Community (indicate name)

- i. APDI
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken..... NO

11. Investigation carried out by

☒ Foot ☒ Boat ☐ Aircraft

12. Remarks/Recommendation..... AREA REQUIRES IMMEDIATE
CLEANUP. NADC SHOULD IMPROVE ON SURVEILLANCE
OF ITS ASSETS AND MORE COMMUNITY INCLUSION

13. Time investigation ended..... 18:50 HRS.