


PICTURES TAKEN AT SITE:

SPILL POINT AFTER EXCAVATION: fig1



SPILL POINT DURING REPAIRS SHOWN: fig2



SPILL POINT AFTER REPAIR: fig3

