



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: SHELL PETROLEUM DEVELOPMENT CO. LTD.
2. Type of Complaint/Incident:
☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify) NON - LEAK.
3. Incident Details
i. Date of Incident: 19/05/18 ii. Date first reported:
iii. Date of first investigation: 25/09/18 iv. Spill Incident No: 2081496
v. Date of follow-up investigation:
vi. Time investigation started: 13:54 HRS
vii. Estimated quantity spilled(bbls): viii. Quantity Recovered:
4. Site Details
i. Site/Location: 2A" TRANS-KAMOS PIPELINE @ OGBOBO
ii. State: BAYELSA iii. L.G.A: EKEREKOR
iv. Spill Co-Ordinates: N(m) 5.02905
E(m) 5.51463
v. Spill area
☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (specify)
iv. Structural Controls in Place
☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify) N/A
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock
ii. Type of Oil contaminant
☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (specify) NON - LEAK
iii. Facility
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify)
iv. Cause of Spill
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify)
v. Visible Sign of Third Party Interference
☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify) 6" BALL VALVE INSTALLED @ 12:00 O'CLOCK
POSITION FOR OR THEFT



6. Impact of Incident

i Properties impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
☒ Others (specify)..... N/A

ii. Nature of impact

- ☒ Oil stained vegetation
☒ Oil stained fishing nets
☒ Dead floating fishes
☒ Dead floating crabs
☒ Withering of vegetation
☒ Others... N/A

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW
☐ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops
☐ Fish Farm/ Pond
☐ Fishing Net
☐ Makeshift
☐ Permanent
☐ Others

8. Extent of Impact

a) Community (indicate name)

- i. Ogbotoso
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

- ☐ Tidal
☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

- ☐ Tidal
☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

- ☐ Tidal
☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken.....

N/A

11. Investigation carried out by

☒ Foot ☒ Boat ☐ Aircraft

12. Remarks/Recommendation.....

SPDC TO IMPROVE ON
SURVEILLANCE OF ITS ASSETS.

13. Time investigation ended.....

14:15 HRS.

14. Name and Signature of Investigator.....