

9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken..... NONE

11. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

12. Remarks/Recommendation (1) Immediate clean up of the affected environment should be carried out by septat. to be duly monitored by NOSDRA. (2) Sewer pit operators should be pro-active to avoid future occurrence.

13. Time investigation ended..... 2:25pm

14. Name and Signature of Participants

PHONE NO