



National Oil Spill Detection & Response Agency

FORM B

RISK BASED ASSESSMENT OF OIL SPILL INCIDENCE (RBA)

Note: This report must be submitted within 2 weeks of Spill Incidence

1. GENERAL INFORMATION:			
i. Company Name:		NIGERIAN PIPELINES AND STORAGE COMPANY	
ii. Date of Assessment:			
iii. Incident Details:	Date of Incidence (dd/mm/yy)	Date spill was stopped	Method Used
	16/06/19	22/06/19	☒ Clamping ☐ Well Shut-in ☐ Valve Shut-in ☐ F/Station Shut down ☐ Others (specify).....
iv. Estimated quantity spilled:		NOT YET QUANTIFIED	
v. Estimated quantity recovered:		NOT YET QUANTIFIED	
vi. Cause of Spill			
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident ☐ Operational Error ☐ Others (specify).....			
2. Site Details			
i. Site Name:		OML: ATC-MDS PIPELINE	
ii. GPS FIELD POINTS Total Length _____ m		Length Surveyed _____ m Differential GPS Yes/No	
Spill Start Point GPS: EASTINGS _____ meters		NOTHINGS _____ meters	
Spill End Point GPS: EASTINGS _____ meters		NOTHINGS _____ meters	
iii. Site area			
☐ Land Swamp ☒ Freshwater ☐ Mangrove ☐ Coastline ☐ Near Shore ☐ Offshore ☐ Others (Specify).....			
iv. Facility			
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig ☐ Storage Tank ☐ Compressor Plant ☐ Others (Specify).....			
v. Site Characterization			
a. Sea Conditions			
☐ Calm ☐ Rough ☒ Not Applicable ☐ Low Tide ☐ High Tide Current direction: Swell Height: Current Strength:			
b. Weather Conditions			
☐ Bright Sunny ☐ Partly Cloudy ☐ Slight rain ☐ Others (Specify)..... Temperature: Wind Direction: Wind Speed: Relative Humidity:			
vi. Visual Observation of Impacted area			
(i) Any oil sheen on water		Yes	☐ No ☐ N/A ☐
(ii) Any oil sheen on water		Yes	☐ No ☐ N/A ☐
(iii) Any oil sheen on water		Yes	☐ No ☐ N/A ☐
(iv) Any oil sheen on water		Yes	☐ No ☐ N/A ☐
(v) Any oil sheen on water		Yes	☐ No ☐ N/A ☐

