

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... Nil.....

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation.....

Repair failed valve and repair the ruptured flow line. Cleanup impacted area. Carry out damage assessment of third party.....