



1. Company: NIGERIA AGIP OIL COMPANY

☒ Others (Specify) GAS/CONDENSATE

vii. Estimated quantity spilled (bbl): 20 Litres viii. Quantity Recovered: Nil

iv. Spill Co-Ordinates: N(m) 04° 53' 09.6"
E(m) 005° 56' 46.0"

☒ Near shore ☒ Offshore ☒ Others (specify).....

☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify) N/A

☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock

☒ Others (specify) _____

☐ Storage Tank ☒ Compressor Plant ☒ Others (specify) _____

☒ Operational Error ☒ Others (specify).....

X Others (specify): _____



6. Impact of Incident

i. Properties impacted by the incident

☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water
☒ Venerable Objects ☒ Others (specify).....

ii. Nature of impact

☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes
☒ Dead floating crabs ☒ Withering of vegetation ☒ Others.....

iii. Delineation of impacted area

☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

☒ Crops ☒ Fish Farm Pond ☒ Fishing Net ☒ Makeshift
☒ Permanent ☒ Others N/A.....

8. Extent of Impact

a) Community (indicate name)

i.
 ii. N/A
 iii.
 iv.

b) Land (indicate area in m²)

i. 1,135.64 m²
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

10. Samples taken..... NONE

11. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

12. Remarks/Recommendation UNKNOWN PERSON(S) CUT THE LINE
WITH HACKSAW AND USED EXPLOSIVE TO RIP - THE - LINE
OPEN INTO TWO.

13. Time investigation ended..... 14:50 HRS