



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY
2. Type of Complaint/Incident:
☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify).....
3. Incident Details
i. Date of Incident: 30 / 01 / 19 ii. Date first reported: 30 / 01 / 2019
iii. Date of first investigation: 03 / 02 / 19 iv. Spill Incident No: 2019/SAR/010
v. Date of follow-up investigation: 06 / 03 / 2019
vi. Time investigation started: 09:20 HRS
vii. Estimated quantity spilled(bbls): 6.17 BBLs viii. Quantity Recovered: YTD
4. Site Details
i. Site/Location: 24" OGODA/BRASS P/L @ FANTUO
ii. State: BAYELSA iii. L.G.A: BRASS
iv. Spill Co-Ordinates: N(m) 04° 24' 11"
E(m) 006° 20' 40.8"
v. Spill area
☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (specify).....
iv. Structural Controls in Place
☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify).....
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock ☒ 7 O' Clock
ii. Type of Oil contaminant
☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (specify)
- iii. Facility
☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant ☒ Others (specify).....
- iv. Cause of Spill
☐ Corrosion ☐ Equipment Failure ☐ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify).....
- v. Visible Sign of Third Party Interference
☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify).....



FACILITY
IS
SUBMERGED

YET TO
BE
DETERMINED

6. Impact of Incident

i Properties impacted by the incident

- ☒Farmland ☒Fish Pond ☒Vegetation ☒Fishing Net ☒Surface water
☒Venerable Objects ☒Others (specify).....

ii. Nature of impact

- ☐Oil stained vegetation ☐Oil stained fishing nets ☐Dead floating fishes
☐Dead floating crabs ☐Withering of vegetation ☐Others.....

iii. Delineation of impacted area

- ☒Within Company's facility/ROW ☐Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops ☐ Fish Farm/ Pond ☐ Fishing Net ☐ Makeshift
☐ Permanent ☐ Others

8. Extent of Impact

a) Community (indicate name)

- i. FANTUO
ii.
iii.
iv.

b) Land (indicate area in m²)

- i. 206 432 m²
ii.
iii.
iv.

b) Creeks/Creek lets

- ☒Tidal ☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

- ☐Tidal ☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

- ☐Tidal ☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

10. Samples taken.....

11. Investigation carried out by

☐ Foot ☒ Boat ☐ Aircraft

12. Remarks/Recommendation (i) CAUSE OF SPILL SHOULD BE ESTABLISHED BEFORE REPAIR. (ii) IMMEDIATE REPAIR OF INCIDENT FACILITY (iii) THERE MAY BE NEED FOR RE-ASSESSMENT TO ASCERTAIN EXTENT OF IMPACT SHOULD THERE BE DELAY IN REPAIR.

13. Time investigation ended.....