

ME PHOTOGRAPHS TAKEN DURING THE JOINT INVESTIGATION VISIT



A: Incident Area



Fig B: Impacted Area



Fig C: Oil Spill Impacted Area



Fig D: Dead Floating Fish




Fig E&F: Containment

Fig G: Recovery Barge