

SOME PHOTOGRAPHS TAKEN DURING THE JOINT INVESTIGATION VISIT



Fig A: Incident Area on arrival of the JIT



Fig B: The Incident Facility after excavation



Fig C: Incident Facility after repair



Fig D: Adjoining Environment