

## SOME PHOTOGRAPHS TAKEN DURING THE JOINT INVESTIGATION VISIT




Fig A: Incident Area on arrival of the JIT




Fig B: The Leak Point/Incident Facility



Fig C: Incident Facility after repair




Fig D: Backfill