



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY (NAOC)

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....

3. Incident Details

- i. Date of Incident: 09/11/18 ii. Date first reported: 09/11/2018
iii. Date of first investigation: 09/11/2018 iv. Spill Incident No: 2018/SAR/049
v. Date of follow-up investigation: 21/11/2018
vi. Time investigation started:.....
vii. Estimated quantity spilled(bbls): 206BBLs viii. Quantity Recovered: 199.62BBLs

4. Site Details

- i. Site/Location: 24" BRASS MANIFOLD/BRASS PIL @ OKPOAMA
ii. State: BAYELSA iii. L.G.A.: BRASS
iv. Spill Co-Ordinates: N(m) 04° 22' 12.2"
E(m) 006° 16' 47.2"

v. Spill area

- ☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....

iv. Structural Controls in Place

- ☒ Boom ☐ Trenches ☒ Bund wall ☐ Sorbents ☒ Others (specify) SHUT-IN

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☒ 6 O' Clock

ii. Type of Oil contaminant

- ☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify)

iii. Facility

- ☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....

iv. Cause of Spill

- ☒ Corrosion ☐ Equipment Failure ☐ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify).....

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (specify).....



6. Impact of Incident

i Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☒ Withering of vegetation ☐ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops ☐ Fish Farm/ Pond ☐ Fishing Net ☐ Makeshift
☐ Permanent ☐ Others

8. Extent of Impact

a) Community (indicate name)

- i. FANTUO
 ii. OKPOAMA
 iii. /
 iv. /

b) Land (indicate area in m²)

- i. 3179 m²
 ii. /
 iii. /
 iv. /

b) Creeks/Creek lets

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. **Photograph/Map/Chart Ref.**

☒ Still photographs ☐ Video coverage ☐ Mapping

10. **Samples taken**.....

11. **Investigation carried out by**

☒ Foot ☒ Boat ☐ Aircraft

12. **Remarks/Recommendation**.....

.....

.....

13. **Time investigation ended**.....