



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

*Note: This JIV Form is to be completed and signed by all participating parties in the field*

1. Company: NIGERIAN AGIP OIL COMPANY (NAOC)
2. Type of Complaint/Incident:  
☒ Oil Pollution    ☒ Fire/Explosion    ☒ Drilling Mud/Chemical Pollution  
☒ Others (Specify).....
3. Incident Details
  - i. Date of Incident: 24 / 04 / 2019 ii. Date first reported: 24 / 04 / 2019
  - iii. Date of first investigation: ..... iv. Spill Incident No: 2019/SAR/037/087
  - v. Date of follow-up investigation: .....
  - vi. Time investigation started: 3:00 PM
  - vii. Estimated quantity spilled(bbls): 20BBL viii. Quantity Recovered: NIL
4. Site Details
  - i. Site/Location: 10" CLOUGH CREEK TEBIDABA P/L AT GBARAUN.
  - ii. State: BAYELSA STATE iii. L.G.A: SOUTHERN ITAW LGA
  - iv. Spill Co-Ordinates: N(m) LAT N 04° 44' 20.2"  
E(m) Lon E 005° 50' 16.8"
  - v. Spill area  
☒ Land    ☒ Swamp    ☒ Freshwater    ☒ Mangrove    ☒ Coastline  
☒ Near shore    ☒ Offshore    ☒ Others (specify).....
  - iv. Structural Controls in Place  
☒ Boom    ☒ Trenches    ☒ Bund wall    ☒ Sorbents    ☒ Others (specify).....
5. Circumstances Around Spill Point
  - i. Visual observation of Hole Position  
☒ 12 O' Clock    ☒ 10 O' Clock    ☒ 2 O' Clock    ☒ 3 O' Clock  
☒ 4 O' Clock    ☒ 5 O' Clock    ☒ 6 O' Clock
  - ii. Type of Oil contaminant  
☒ Crude Oil    ☒ Condensate    ☒ Chemicals    ☒ Refined Products  
☒ Others (specify) .....
  - iii. Facility  
☒ Pipeline    ☒ Flow line    ☒ Wellhead    ☒ Manifold    ☒ Flow Station    ☒ Rig  
☒ Storage Tank    ☒ Compressor Plant    ☒ Others (specify).....
  - iv. Cause of Spill  
☒ Corrosion    ☒ Equipment Failure    ☒ Third Party Interference    ☒ Accident  
☒ Operational Error    ☒ Others (specify).....
  - v. Visible Sign of Third Party Interference  
☒ Hacksaw Marks    ☒ Drilled Holes    ☒ Blasting    ☒ Theft    ☒ Acid  
☐ Others (specify).....



## 6. Impact of Incident

### i. Properties impacted by the incident

- ☒ Farmland   ☐ Fish Pond   ☒ Vegetation   ☒ Fishing Net   ☒ Surface water  
☒ Venerable Objects   ☒ Others (specify).....

### ii. Nature of impact

- ☒ Oil stained vegetation   ☒ Oil stained fishing nets   ☒ Dead floating fishes  
☒ Dead floating crabs   ☒ Withering of vegetation   ☒ Others.....

### iii. Delineation of impacted area

- ☒ Within Company's facility/ROW   ☒ Outside Company's facility/ROW

## 7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops   ☒ Fish Farm/ Pond   ☒ Fishing Net   ☒ Makeshift  
☒ Permanent   ☒ Others .....

## 8. Extent of Impact

### a) Community (indicate name)

- i. ....  
ii. ....  
iii. ....  
iv. ....

### b) Land (indicate area in $m^2$ )

- i. ....  
ii. ....  
iii. ....  
iv. ....

### b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### c) Swamp

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### d) River

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### e) Shoreline/water

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

9. Photograph/Map/Chart Ref.

☒ Still photographs

☒ Video coverage

☐ Mapping

10. Samples taken.....

11. Investigation carried out by

☒ Foot

☐ Boat

☐ Aircraft

12. Remarks/Recommendation.....

CLEAN UP OF IMPACTED SITE SHOULD  
BE DONE AS SOON AS POSSIBLE, TO AVOID FURTHER SPREAD

13. Time investigation ended.....