


PICTURES TAKEN AT SITE:



REPAIR WORK DONE BY NAOC REPAIR TEAM



COMPLETED REPAIR



BOOM ON IMPACTED AREA