



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY LIMITED (NOC)
2. Type of Complaint/Incident:
 - ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
 - ☒ Others (Specify).....
3. Incident Details
 - i. Date of Incident: 04/01/2019 ii. Date first reported: 05/01/2019
 - iii. Date of first investigation: 05/01/2019 iv. Spill Incident No: 2019/01/001
 - v. Date of follow-up investigation:
 - vi. Time investigation started: 13:30 HRS
 - vii. Estimated quantity spilled(bbls): 178bbls viii. Quantity Recovered: 2bbls
4. Site Details 10" LOUGH CREEK / TERBIDABA PIPELINE AT GBARAUN
 - i. Site/Location:
 - ii. State: BAYELSA iii. L.G.A: SOUTHERN IJAW
 - iv. Spill Co-Ordinates: N(m) 04° 46' 41.1"
E(m) 005° 46' 54.5"
 - v. Spill area
 - ☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
 - ☒ Near shore ☒ Offshore ☒ Others (specify).....
 - iv. Structural Controls in Place
 - ☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify).....
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
 - ☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
 - ☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock (3' o'clock - 5' o'clock) ✓
 - ii. Type of Oil contaminant
 - ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
 - ☒ Others (specify)
 - iii. Facility
 - ☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
 - ☒ Storage Tank ☒ Compressor Plant ☒ Others (specify).....
 - iv. Cause of Spill
 - ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
 - ☒ Operational Error ☒ Others (specify).....
 - v. Visible Sign of Third Party Interference
 - ☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
 - ☒ Others (specify).....



6. Impact of Incident

i Properties impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
☒ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
☒ Dead floating crabs
☒ Withering of vegetation
☒ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW
☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops
☒ Fish Farm/ Pond
☒ Fishing Net
☒ Makeshift
☒ Permanent
☒ Others *Vegetations only.*

8. Extent of Impact

a) Community (indicate name)

- i. *Cibaran*
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☒ Tidal

☒ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

10. Samples taken..... *N.A*

11. Investigation carried out by

☐ Foot ☒ Boat ☐ Aircraft

12. Remarks/Recommendation

*NAOC should be requested to
improve on security before on their facilities.*

13. Time investigation ended

15:45 HRS.

14. Name and Signature of Participants