

PHOTOGRAPHS TAKEN DURING JIV



Fig A: Incident point.



Fig B: Impacted Environment.




Fig C: Shallow pit.



Fig D: After replacement and repair.