



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY (NAOC)
2. Type of Complaint/Incident:
☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☒ Others (Specify) CONDENSATE
3. Incident Details
i. Date of Incident: 4/11/19 ii. Date first reported:/...../.....
iii. Date of first investigation: 09/11/19 iv. Spill Incident No: 2019/LAR/125
v. Date of follow-up investigation:/...../.....
vi. Time investigation started: 11:11 HRS
vii. Estimated quantity spilled(bbls): 16 viii. Quantity Recovered: 1/2 UNKNOWN
4. Site Details
i. Site/Location: 6" TUDMO/BEROMBRI P/L AT AYAMASA
ii. State: BAYELSA STATE iii. L.G.A: EKEREMOR
iv. Spill Co-Ordinates: N(m) 05° 06' 24.7"
E(m) 005° 54' 36.4"
v. Spill area
☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....
iv. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☒ 6 O' Clock 7, clock
ii. Type of Oil contaminant
☐ Crude Oil ☒ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify).....
iii. Facility
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....
iv. Cause of Spill
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify).....
v. Visible Sign of Third Party Interference
☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☒ Others (specify) Cut-off cone



6. Impact of Incident

i Properties impacted by the incident

- ☒ Farmland
 ☐ Fish Pond
 ☒ Vegetation
 ☐ Fishing Net
 ☐ Surface water
☐ Venerable Objects
 ☐ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation
 ☐ Oil stained fishing nets
 ☐ Dead floating fishes
☐ Dead floating crabs
 ☐ Withering of vegetation
 ☐ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW
 ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops
 ☒ Fish Farm/ Pond
 ☐ Fishing Net
 ☐ Makeshift
☐ Permanent
 ☐ Others

8. Extent of Impact

a) Community (indicate name)

- i. Aydausa
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i. 8,075.75
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	N/A	A	

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	N/A	A	

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	N/A	A	

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	N/A	A	

9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken.....

11. Investigation carried out by

☒ Foot ☒ Boat ☐ Aircraft

12. Remarks/Recommendation

Urgent Clean-up is needed
NDOC should increase surveillance of her facilities
TIV was conclusive.

13. Time investigation ended.....