

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY JOINT INVESTIGATION VISIT (JIV) FORM

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: **NIGERIAN AGIP OIL COMPANY (NAOC.)**
2. Type of Complaint/Incident:
 - ☐ Oil Pollution
 - ☐ Fire/Explosion
 - ☐ Drilling Mud/Chemical Pollution
 - ☒ Others (Specify) **Crude oil spill**
3. Incident Details
 - i. Date of Incident: **14 09 19**
 - ii. Date first reported: **15 09 2019**
 - iii. Date of first investigation: **16 09 2019**
 - iv. Spill Incidence No: **2019/SAH/069**
 - v. Date of follow-up investigation:
 - vi. Time investigation started: **1541 HRS**
 - vii. Estimated quantity spilled(bbls): **0.09**
 - viii. Quantity Recovered: **NIL**
4. Site Details
 - i. Site/Location: **18th ORANGA/BRASS P/L @ ADIKIAMA**
 - ii. State: **BAYELSA STATE**
 - iii. LGA: **NEMBE**
 - iv. Spill Co-ordinates: N(m) **04° 32' 15.1"**
 - E(m) **006° 15' 36.5"**
 - v. Spill area
 - ☐ Land
 - ☒ Swamp
 - ☐ Freshwater
 - ☐ Mangrove
 - ☐ Coastline
 - ☐ Near shore
 - ☐ Offshore
 - ☐ Others (specify)
 - vi. Structural Controls in Place
 - ☐ Boom
 - ☐ Trenches
 - ☐ Bund wall
 - ☐ Sorbents
 - ☐ Others (specify)
- Circumstances Around Spill Point
 - i. Visual observation of Hole Position
 - ☒ 12 O' Clock
 - ☐ 10 O' Clock
 - ☐ 2 O' Clock
 - ☐ 3 O' Clock
 - ☐ 4 O' Clock
 - ☐ 5 O' Clock
 - ☐ 6 O' Clock
 - ii. Type of Oil contaminant
 - ☒ Crude Oil
 - ☐ Condensate
 - ☐ Chemicals
 - ☐ Refined Products
 - ☐ Others (specify)
 - iii. Facility
 - ☒ Pipeline
 - ☐ Flow line
 - ☐ Wellhead
 - ☐ Manifold
 - ☐ Flow Station
 - ☐ Rig
 - ☐ Storage Tank
 - ☐ Compressor Plant
 - ☐ Others (specify)
 - iv. Cause Of Spill
 - ☐ Collision
 - ☐ Equipment Failure
 - ☒ Third Party Interference
 - ☐ Accident
 - ☐ Operational Error
 - ☐ Others (specify)
 - v. Visible Sign of Third Party Interference
 - ☐ Hacking Marks
 - ☐ Drilled Holes
 - ☐ Blasting
 - ☒ Theft
 - ☐ Acid
 - ☐ Others (specify)



6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farm and ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify) _____

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☒ Dead floating crabs ☐ Withering of vegetation ☒ Others (Specify) _____

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

i. ADIKIAMA

(b) Land (Indicate area in m²)

i. 143 m²

ii. _____

iii. _____

iv. _____

(c) Creek/Creek Est.

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	N/A		

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	N/A		

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	N/A		

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	N/A		

9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken.....

11. Investigation carried out by

☒ Foot ☒ Boat ☐ Aircraft

12. Remarks/Recommendation.....

Tiv was conclusive, NAOC should increase surveillance of her facilities.

13. Time investigation ended.....