

Inc no. 2020 / ~~ML~~ / LA / 0044

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NADC

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)

3. Incident Details

- i. Date of Incident: 04/03/2020 ii. Date first reported:
iii. Date of first investigation: 05/03/2020
iv. Date of follow-up investigation:
v. Time investigation started: 13:56 hrs.
vi. Estimated quantity spilled: MIL

4. Site Details

- i. Site/Location: 24" Opode-Brass P/L @ Okogbe
ii. Position of Spill/Leak: N05°03'33.5" E006°33'04.8"
iii. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify) none

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
☐ Others (Specify) 2" Valve seen installed on P/L

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify) *n/A*

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify) *n/A*

iii. Delineation of Impacted area

- ☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

i. *Okogba*

ii.

iii.

iv.

(b) Land (Indicate area in m²)

i. *n/A*

ii.

iii.

iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>[Handwritten line]</i>	<i>[Handwritten line]</i>	<i>[Handwritten line]</i>	<i>[Handwritten line]</i>
<i>[Handwritten line]</i>	<i>[Handwritten line]</i>	<i>[Handwritten line]</i>	<i>[Handwritten line]</i>
<i>[Handwritten line]</i>	<i>[Handwritten line]</i>	<i>[Handwritten line]</i>	<i>[Handwritten line]</i>
<i>[Handwritten line]</i>	<i>[Handwritten line]</i>	<i>[Handwritten line]</i>	<i>[Handwritten line]</i>

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>[Handwritten line]</i>	<i>[Handwritten line]</i>	<i>[Handwritten line]</i>	<i>[Handwritten line]</i>
<i>[Handwritten line]</i>	<i>[Handwritten line]</i>	<i>[Handwritten line]</i>	<i>[Handwritten line]</i>
<i>[Handwritten line]</i>	<i>[Handwritten line]</i>	<i>[Handwritten line]</i>	<i>[Handwritten line]</i>
<i>[Handwritten line]</i>	<i>[Handwritten line]</i>	<i>[Handwritten line]</i>	<i>[Handwritten line]</i>

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>[Handwritten line]</i>	<i>[Handwritten line]</i>	<i>[Handwritten line]</i>	<i>[Handwritten line]</i>
<i>[Handwritten line]</i>	<i>[Handwritten line]</i>	<i>[Handwritten line]</i>	<i>[Handwritten line]</i>
<i>[Handwritten line]</i>	<i>[Handwritten line]</i>	<i>[Handwritten line]</i>	<i>[Handwritten line]</i>
<i>[Handwritten line]</i>	<i>[Handwritten line]</i>	<i>[Handwritten line]</i>	<i>[Handwritten line]</i>

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>[Handwritten line]</i>	<i>[Handwritten line]</i>	<i>[Handwritten line]</i>	<i>[Handwritten line]</i>
<i>[Handwritten line]</i>	<i>[Handwritten line]</i>	<i>[Handwritten line]</i>	<i>[Handwritten line]</i>
<i>[Handwritten line]</i>	<i>[Handwritten line]</i>	<i>[Handwritten line]</i>	<i>[Handwritten line]</i>
<i>[Handwritten line]</i>	<i>[Handwritten line]</i>	<i>[Handwritten line]</i>	<i>[Handwritten line]</i>

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... *N/A*

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation

2" valve was seen installed on PK @ 12 o'clock position by unknown persons for theft purpose. Camm. by rep. refused to sign JUV for because he was not given money. There is need for increased surveillance and security.

12. Time Investigation ended

15:30 hrs