

**CRUDE OIL/PRODUCT/CHEMICAL SPILL AND CONTAMINATION CLEAN-UP
CERTIFICATION.**

COMPANY: THE SHELL PETROLEUM DEVELOPMENT COMPANY NIGERIA LIMITED.

PART A.

- 1.0 DATE OF INSPECTION: 21/05/2015
- 1.1 LOCATION: 10" Diesel Creek - NUNRPL @ Onyoma INC. NO: 2014-1201770
- 1.2 HOW MANY SPILLS HAVE OCCURRED FROM THIS LOCATION IN THE
- (A) CURRENT YEAR?
- (B) PREVIOUS YEARS?

2.0 INSPECTION TEAM MEMBERS:

- (i) Alhassan Abubakar 21/05/2015 - DPR
- (ii) KOMI ABAM 21/05/2015 NISRA
- (iii) Ajike Awudung 21/05/2015 BYONE
- (iv) Chima Agomuo 21/05/2015 SPDC-REM
- (v) Okabisi, Emmanuel TOL 21/5/15
- (vi) Okot, H SPDC 21/05/15

3.0 DETAILS OF SPILL:

- 3.1 Date of Spill: 25/06/2014
- 3.2 Cause of Spill: Third Party Interference
- 3.3 Qty Spilled: 367 bbls
- 3.4 Qty Recovered: 317 bbls
- 3.5 Clean-up Period: (25/06/14 to 19/05/15)
- 3.6 Delimitation of Impacted Areas: (Graphic)

4.0 FINDINGS:

4.1 VISUAL OBSERVATIONS: (TICK AS APPROPRIATE):

- (i) Any Oil Sheen on Water? () YES (✓) NO () NA
- (ii) Any Oil Stain on Vegetation? () YES (✓) NO () NA
- (iii) Is Soil Wet with Oil? () YES (✓) NO () NA
- (iv) Any Patches of Oil in Impacted Area? () YES (✓) NO () NA
- (v) Any Oil Sheen when Soil Sediment is disturbed? () YES (✓) NO () NA

CRUDE OIL/PRODUCT/CHEMICAL SPILL AND CONTAMINATION CLEAN-UP CERTIFICATION.

COMPANY: THE SHELL PETROLEUM DEVELOPMENT COMPANY NIGERIA LIMITED.

PART A.

(vi) Is Disposal of oil Debris Satisfactory? ☒ YES () NO () NA

(vii) Was Dispersant Applied () YES () NO ☒ NA

4.2 RESULTS OF LABORATORY ANALYSES FOR SAMPLES COLLECTED FROM IMPACTED MEDIUM/MEDIA.

S/N	PARAMETERS	RESULT OF IMPACTED ENVIRONMENT (MEDIUM/MEDIA)					
		SEDIMENT/SOIL		SURFACE WATER		UNDERGROUND WATER	
		Sample	Control	Sample	Control	Sample	Control
1	PH						
2	Polyaromatic Hydrocarbons						
	- Benzene						
	- Toluene						
	- Ethyl						
	- Benzene						
	- xylene						
3	THC						
4	Sulphide						
5	COD						
6	Lead						
7	Nickel						
8	Vanadium						
9	Chromium (Total)						

(Attached Sample Location Map)

5.0 COMMENTS/DISCUSSION Visually Clean-up is satisfactory.

6.0 RECOMMENDATION final certification subject to laboratory result of samples collected.

7.0 CONCLUSION INDICATE WHETHER THE CLEAN-UP IS CERTIFIED AS:

(i) SATISFACTORY ☒

(ii) NOT SATISFACTORY ()

8.0 SIGNATURES

OPERATOR/LICENCEE/DRILLER

DPR REP.

CLEAN-UP SUPERVISOR

Ukonwan O.
Ogasere (SPOC)

[Handwritten signatures]