



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY  
JOINT INVESTIGATION VISIT (JIV) FORM**

*Note: This JIV form is to be completed and signed by all participating parties in the field*

1. Company: S PDC - ID 2600329

2. Type of Complaint/Incident:

- ☒ Oil Pollution    ☐ Fire/Explosion    ☐ Drilling Mud/Chemical Pollution  
☐ Others (Specify) .....

3. Incident Details

- i. Date of Incident: 11-03-2020 ii. Date first reported: .....  
iii. Date of first investigation: 12-03-2020 .....  
iv. Date of follow-up investigation: .....  
v. Time investigation started: 14:40 H2S .....  
vi. Estimated quantity spilled: 2 Barrels .....

4. Site Details

- 28" NEPOKU - BOMU T/L N. RUEPOKINU COMM OBIAKPOLE LAD RIVER SIDE  
i. Site/Location: N 04° 56' 17.49" E 007° 1' 19.64" .....  
ii. Position of Spill/Leak: N 04° 56' 17.49" E 007° 1' 19.64" .....  
iii. Spill area

- ☒ Land    ☐ Swamp    ☐ Freshwater    ☐ Mangrove    ☐ Coastline  
☐ Near shore    ☐ Offshore    ☐ Others (Specify) .....

iv. Structural Controls in Place

- ☐ Boom    ☐ Trenches    ☐ Bund Wall    ☒ Sorbents    ☐ Others (Specify) .....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock    ☐ 10 O'Clock    ☐ 2 O'Clock    ☐ 3 O'Clock  
☐ 4 O'Clock    ☐ 5 O'Clock    ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil    ☐ Condensate    ☐ Chemicals    ☐ Refined Products  
☐ Others (Specify) .....

iii. Facility

- ☐ Pipeline    ☐ Flow Line    ☐ Wellhead    ☐ Manifold    ☐ Flow Station    ☐ Rig  
☐ Storage Tank    ☐ Compressor Plant  
☐ Others (Specify) .....

iv. Cause of Spill

- ☐ Corrosion    ☐ Equipment Failure    ☒ Third Party Interference    ☐ Accident  
☐ Operational Error    ☐ Others (Specify) .....

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks    ☐ Drilled Holes    ☐ Blasting    ☒ Theft    ☐ Acid  
☐ Others (Specify) .....

## 6. Impact of Incident

### i. Properties Impacted by the Incident

- ☐ Farmland   ☐ Fish Pond   ☐ Vegetation   ☐ Fishing Net   ☐ Surface water  
☐ Venerable Objects   ☐ Others (Specify) ROAD

### ii. Nature of Impact

- ☐ Oil stained vegetation   ☐ Oil stained fishing nets   ☐ Dead floating fishes  
☐ Dead floating crabs   ☐ Withering of vegetation   ☒ Others (Specify) .....

### iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW   ☐ Outside Company's facility/ROW

## 7. Extent of Impact

### (a) Community (Indicate name)

- i. /  
 ii. /  
 iii. /  
 iv. /

### (b) Land (Indicate area in m<sup>2</sup>)

- i. /  
 ii. /  
 iii. /  
 iv. /

### (c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

| NAME     | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|----------|--------------------|-----------------|----------------|
| <u>/</u> | <u>/</u>           | <u>/</u>        | <u>/</u>       |
| <u>/</u> | <u>/</u>           | <u>/</u>        | <u>/</u>       |
| <u>/</u> | <u>/</u>           | <u>/</u>        | <u>/</u>       |
| <u>/</u> | <u>/</u>           | <u>/</u>        | <u>/</u>       |

### (d) Swamp

☐ Tidal

☐ Non-tidal

| NAME     | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|----------|--------------------|-----------------|----------------|
| <u>/</u> | <u>/</u>           | <u>/</u>        | <u>/</u>       |
| <u>/</u> | <u>/</u>           | <u>/</u>        | <u>/</u>       |
| <u>/</u> | <u>/</u>           | <u>/</u>        | <u>/</u>       |
| <u>/</u> | <u>/</u>           | <u>/</u>        | <u>/</u>       |

### (e) River

☐ Tidal

☐ Non-tidal

| NAME     | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|----------|--------------------|-----------------|----------------|
| <u>/</u> | <u>/</u>           | <u>/</u>        | <u>/</u>       |
| <u>/</u> | <u>/</u>           | <u>/</u>        | <u>/</u>       |
| <u>/</u> | <u>/</u>           | <u>/</u>        | <u>/</u>       |
| <u>/</u> | <u>/</u>           | <u>/</u>        | <u>/</u>       |

### (f) Shoreline/water

☐ Tidal

☐ Non-tidal

| NAME     | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|----------|--------------------|-----------------|----------------|
| <u>/</u> | <u>/</u>           | <u>/</u>        | <u>/</u>       |
| <u>/</u> | <u>/</u>           | <u>/</u>        | <u>/</u>       |
| <u>/</u> | <u>/</u>           | <u>/</u>        | <u>/</u>       |
| <u>/</u> | <u>/</u>           | <u>/</u>        | <u>/</u>       |

8. Photograph/Map/Chart Ref.

☒ Still photographs   ☐ Video coverage   ☐ Mapping

9. Samples taken .....

10. Investigation carried out by

☒ Foot   ☐ Boat   ☐ Aircraft

11. Remarks/Recommendation. *Immediate repairs and cleanup*  
*of impacted area is highly recommended.*

12. Time Investigation ended .....

13. Name and Signature of Participants .....