

SPDC/1214762

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: SPDC

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)

3. Incident Details

- i. Date of Incident: 15/07/14 ii. Date first reported: 15/07/14
iii. Date of first investigation: 18/07/14
iv. Date of follow-up investigation:
v. Time investigation started: 11:40 AM
vi. Estimated quantity spilled: 355L

4. Site Details

- i. Site/Location: 4" SANTA BARBARA WELL 11T F/L
ii. Position of Spill/Leak: N 4° 32' 22.8" E 6° 31' 23.7"

iii. Spill area

- ☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☒ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)

iii. Facility

- ☐ Pipeline ☒ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (Specify)

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify)

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify)

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

(b) Land (Indicate area in m²)

- i. i. ... 0.14 m²
ii. ii.
iii. iii.
iv. iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken.....Nil.....

10. Investigation carried out by

☐ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation..... A black saw-cut measuring
about 5cm was observed on the G⁴ F.I.C. at Santa Barbara.
SPDC should strengthen surveillance of its facilities.....

12. Time Investigation ended.....