



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

- 14
1. Company: Infra-Vision Limited
 2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....
 3. Incident Details
i. Date of Incident: 15/06/2020 ii. Date first reported: 18/07/2020
iii. Date of first investigation: 19/07/2020
iv. Date of follow-up investigation:.....
v. Time investigation started: 1105 hours
vi. Estimated quantity spilled: 38 barrels
 4. Site Details
i. Site/Location: Kurmin Tibin Kagarko Lga (N)
ii. Position of Spill/Leak.....
iii. Spill area
☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....
iv. Structural Controls in Place
☐ Boom ☒ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....
 5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
ii. Type of Oil contaminant
☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☒ Others (specify) AGO (Diesel)
iii. Facility
☐ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☒ Others (specify) Tanker Truck
iv. Cause Of Spill
☐ Corrosion ☐ Equipment Failure ☐ Third Party Interference ☒ Accident
☐ Operational Error ☐ Others (specify).....
v. Visible Sign of Third Party Interference
☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☒ Others (specify) not applicable

6. Impact of Incident

i. Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify).....

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☒ Withering of vegetation ☐ Others.....

iii. Delineation of impacted area

- ☐ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

- i. Kurmin Jabin
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i. Kurmin Jabin
 ii.
 iii.
 iv.

b) Creeks/Creek lets ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☒ Mapping

9. Samples taken

Nil

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft


11. Remarks/Recommendation

Immediate clean-up and re-mediation of the impacted site.

12. Time investigation ended

13. Name and Signature of Participants

❖ NOSDRA

1. Ewur H. A.  19/07/2020
2. Ali Bolani Adams  19/07/2020
3. David Ameh Reuben  19/07/2020

❖ DPR

- 1.
- 2.
- 3.



❖ STATE MINISTRY OF ENVIRONMENT

- 1.
- 2.
- 3.



❖ LOCAL GOVERNMENT COUNCIL

- 1.
- 2.
- 3.

❖ COMPANY

1. Richard Dammy Oadani  19/07/2020
2. Durojaiye Simeon
3. AKINPELU AKINSHOLA  19/07/2020

❖ COMMUNITY

1. James N. GUNGBAKI  19/7/2020
2. OLUKOTI GAIYA  19/7/2020
3. EZEKIEL E. HARIBE  19/7/2020