



24

**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

*Note: This JIV Form is to be completed and signed by all participating parties in the field*

1. Company: KAMLIK NIGERIA LIMITED
2. Type of Complaint/Incident:  
☒ Oil Pollution    ☐ Fire/Explosion    ☐ Drilling Mud/Chemical Pollution  
☐ Others (Specify).....
3. Incident Details  
i. Date of Incident: 22/07/2020    ii. Date first reported: 22/07/2020  
iii. Date of first investigation: 23/07/2020  
iv. Date of follow-up investigation:.....  
v. Time investigation started: 10:45 am  
vi. Estimated quantity spilled: 500 LITERS (3 BARRELS APPROXIMATELY)
4. Site Details  
i. Site/Location: KAMLIK NIG LTD FILLING STATION/NID 53848° E007.40969°  
ii. Position of Spill/Leak:.....  
iii. Spill area  
☒ Land    ☐ Swamp    ☐ Freshwater    ☐ Mangrove    ☐ Coastline  
☐ Near shore    ☐ Offshore    ☐ Others (specify).....  
iv. Structural Controls in Place  
☐ Boom    ☐ Trenches    ☐ Bund wall    ☐ Sorbents    ☐ Others (specify).....
5. Circumstances Around Spill Point  
i. Visual observation of Hole Position  
☐ 12 O' Clock    ☐ 10 O' Clock    ☐ 2 O' Clock    ☐ 3 O' Clock  
☐ 4 O' Clock    ☐ 5 O' Clock    ☐ 6 O' Clock  
ii. Type of Oil contaminant  
☐ Crude Oil    ☐ Condensate    ☐ Chemicals    ☒ Refined Products  
☐ Others (specify) A90 (DIESEL)  
iii. Facility  
☐ Pipeline    ☐ Flow line    ☐ Wellhead    ☐ Manifold    ☐ Flow Station    ☐ Rig  
☐ Storage Tank    ☐ Compressor Plant    ☒ Others (specify) FILLING STATION  
iv. Cause Of Spill  
☐ Corrosion    ☐ Equipment Failure    ☐ Third Party Interference    ☐ Accident  
☐ Operational Error    ☐ Others (specify) underground storage tanks were allegedly forced out by pressure due to flooding.  
v. Visible Sign of Third Party Interference  
☐ Hacksaw Marks    ☐ Drilled Holes    ☐ Blasting    ☐ Theft    ☐ Acid  
☐ Others (specify).....

6. Impact of Incident

i. Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☐ Surface water  
☐ Venerable Objects ☐ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes  
☐ Dead floating crabs ☒ Withering of vegetation ☐ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

- i. ....  
 ii. ....  
 iii. ....  
 iv. ....

b) Land (indicate area in m<sup>2</sup>)

- i. ....  
 ii. ....  
 iii. ....  
 iv. ....

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

c) Swamp

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

d) River

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

e) Shoreline/water

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

Photograph/Map/Chart Ref  
☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken NIL

10. Investigation carried out by  
☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation IMMEDIATE CLEAN-UP AND REMEDIATION.

12. Time investigation ended

13. Name and Signature of Participants

NOSDRA  
1. ALI BUTHARI ADAMU [Signature] 23/07/2020  
2. ABDUL KADIR ABDULLAH MOHAMMED [Signature] 23/07/2020  
3. Ojeh Felix Elejo [Signature] 23/7/2020

DPR

- 1.
- 2.
- 3.

STATE MINISTRY OF ENVIRONMENT

- 1.
- 2.
- 3.

LOCAL GOVERNMENT COUNCIL

1. Usman Muhammed Lawal 070655653872  
2. Jibril Dahiru 08065527628  
3.

COMPANY

[Signature] Mohd Umar Tunpu 08023099666  
[Signature] Mohd Rofiq 0836943603

COMMUNITY

1. Bashir Abdulahi  
2.  
3.