




National Oil Spill Detection & Response Agency

FORM B

RISK BASED ASSESSMENT OF OIL SPILL INCIDENCE (RBA)

Note: This report must be submitted within 2 weeks of Spill Incidence

1. GENERAL INFORMATION:			
i. Company Name:	NPSC		
ii. Date of Assessment:	27/08/2020 (IYANA ODO LAGOS)		
iii. Incident Details:	Date of Incidence (dd/mm/yy)	Date spill was stopped	Method Used
	23/08/2020	23/08/2020	☒ Clamping ☐ Well Shut-in ☐ Valve Shut-in ☐ F/Station Shut down ☐ Others (specify).....
iv. Estimated quantity spilled:	NOT YET QUANTIFIED		
v. Estimated quantity recovered:			
vi. Cause of Spill	☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident ☐ Operational Error ☐ Others (specify).....		
2. Site Details			
i. Site Name:	IYANA ODO LAGOS		OML:
ii. GPS FIELD POINTS Total Length	_____m Length Surveyed _____m Differential GPS Yes/No		
Spill Start Point GPS: EASTINGS	06°32'42.3"		_____meters NOTHINGS _____meters
Spill End Point GPS: EASTINGS	06°32'16.5"		_____meters NOTHINGS 06°32'14.2" _____meters
iii. Site area	☒ Land Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline ☐ Near Shore ☐ Offshore ☐ Others (Specify).....		
iv. Facility	☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig ☐ Storage Tank ☐ Compressor Plant ☐ Others(Specify).....		
v. Site Characterization			
a. Sea Conditions	☐ Calm ☐ Rough ☒ Not Applicable ☐ Low Tide ☐ High Tide Current direction: Swell Height: Current Strength:		
b. Weather Conditions	☒ Bright Sunny ☐ Partly Cloudy ☐ Slight rain ☐ Others (Specify)..... Temperature: Wind Direction: Wind Speed: Relative Humidity:		
vi. Visual Observation of Impacted area			
(i) Any oil sheen on water	Yes	☐ No	☒ N/A ☐
(ii) Any oil sheen on water	Yes	☐ No	☐ N/A ☐
(iii) Any oil sheen on water	Yes	☐ No	☐ N/A ☐
(iv) Any oil sheen on water	Yes	☐ No	☐ N/A ☐
(v) Any oil sheen on water	Yes	☐ No	☐ N/A ☐



Receptor Assessment

Receptor	Pathway to Impacted Area(m ²)	Distance to Impacted Area(m ²)	Estimated Area of Impact Area(m ²)	Receptor (Yes/No)	Impacted	Remarks
Farmland						
Fish Pond						
Vegetation						
Surface Water						
Ground Water						
Venerable Object						
Human Habitation						
Livestock						
Plantation						
Swamp						

vii. Any Casualties

☐ Yes ☒ No

If yes, give details.....

viii. Clean-up Program details

a. Method of clean-up.....

b. Time frame for clean-up.....

ix. General Remarks

REPORTING OFFICER: S. HIRU K

DESIGNATION: For: Supt HSE

SIGNATURE: [Signature]

DATE: 30/03/20

*Clean-up program report must be submitted within 2 weeks of spill incidence.

