



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: SPDC

2. Type of Complaint/Incident: INCIDENT NO. 2781793

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)

3. Incident Details

i. Date of Incident: 11/11/2020 ii. Date first reported:

iii. Date of first investigation: 14/11/2020

iv. Date of follow-up investigation:

v. Time investigation started: 1441 HOURS

vi. Estimated quantity spilled: 10 BARRELS (7 BBLs RECOVERED OUT OF THE 10 BBLs)

4. Site Details

i. Site/Location: 12" IMO-RIVER 1 TO OGAE TRUNKLINE AT OKOHA

ii. Position of Spill/Leak: N4.92805 E007.18469

iii. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify) 3 NONE

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
☒ Others (Specify) LOCALLY FABRICATED CLAMP WITH 1/2" VALVE CONNECTED TO AN ELBOW PIPE; INSTALLED AROUND THE SPILL POINT AT 12 O'CLOCK POSITION.

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify)

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☒ Withering of vegetation ☐ Others (Specify)

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

i. OKOHIA

(b) Land (Indicate area in m²)

i. 0.05 HECTARES

ii.
 iii.
 iv.

(c) Creek/Creek lets ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
NOT APPLICABLE			

(d) Swamp ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
NOT APPLICABLE			

(e) River ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
NOT APPLICABLE			

(f) Shoreline/water ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
NOT APPLICABLE			

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... **NOT APPLICABLE**

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation... **REPAIRS ON THE SPILL POINT COMMENCED IMMEDIATELY AFTER IN. SPDC IS TO INITIATE CLEAN-UP OF THE IMPACTED AREA AS SOON AS POSSIBLE.**

12. Time Investigation ended..... **1545 HOURS**

13. Name and Signature of Participants

❖ NOSDRA

1. **GODSPower ISHEKE** ~~ASB~~ **14/11/2020**

2.

3.

❖ DPR

1. **IGWE LEO IFEAKACHI** ~~KAA~~ **14-11-2020**

2.

3.

❖ STATE MINISTRY OF ENVIRONMENT

1. **ORINUWA SPANIEL** ~~ASB~~ **14-11-2020**

2.

3.

❖ LOCAL GOVERNMENT COUNCIL

1.

2.

3.

❖ COMPANY

1. **Amethyste Emmanuel** ~~ASB~~ **14/11/2020 1600HRS**

2. **Udenna Donprince** ~~ASB~~ **14/11/2020 16.00hrs**

3.

❖ COMMUNITY

1. **Harvey Okey UKhach** ~~ASB~~ **Obioke Town 13/11/20**

2.

3.