2021/LAR/008

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

Company: NAOC

Type of Complaint/Incident:

☑ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution

☑ Others (Specify) CONDENSATE

Incident Details

i. Date of Incident: 03/02/2021 ii. Date first reported: 03/02/2021

iii. Date of first investigation: 04/02/2021

iv. Date of follow-up investigation:

v. Time investigation started:

vi. Estimated quantity spilled: 0.4 barrels

Site Details

i. Site/Location: ~~[illegible]~~ OSHIE WELL 155 F/L @ OSHIE

ii. Position of Spill/Leak: N 05° 8' 19.3" E 006° 28' 56" | N 05° 08' 19.3" E 006° 28' 56.3" | N 05° 08' 19.3" E 006° 28' 56.3" | N 05° 08' 19.3" E 006° 28' 56.3"

iii. **Spill area** N 05° 08' 19.4" E 006° 28' 56.7"

☑ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline

☐ Near shore ☐ Offshore ☐ Others (Specify).....

iv. **Structural Controls in Place**

☐ Boom ☑ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify).....

Circumstances Around Spill Point

i. **Visual observation of Hole Position**

☐ 12 0'Clock ☐ 10 0'Clock ☐ 2 0'Clock ☐ 3 0'Clock

☐ 4 0'Clock ☑ 5 0'Clock ☑ 6 0'Clock

ii. **Type of Oil Contaminant**

☐ Crude Oil ☑ Condensate ☐ Chemicals ☐ Refined Products

☐ Others (Specify) .....

iii. **Facility**

☐ Pipeline ☑ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig

☐ Storage Tank ☐ Compressor Plant

☐ Others (Specify) .....

iv. **Cause of Spill**

☐ Corrosion ☐ Equipment Failure ☑ Third Party Interference ☐ Accident

☐ Operational Error ☐ Others (Specify) .....

v. **Visible Sign of Third Party Interference**

☑ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid

☐ Others (Specify) .....

6. **Impact of Incident**

i. **Properties Impacted by the incident**

☐ Farmland ☐ Fish Pond ☑ Vegetation ☐ Fishing Net ☐ Surface water

☐ Venerable Objects ☐ Others (Specify) .....

ii. **Nature of impact**

☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes

☐ Dead floating crabs ☑ Withering of vegetation ☐ Others (Specify) .....

iii. **Delineation of Impacted area**

☑ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. **Extent of Impact**

(a) **Community** (*Indicate name*) (b) **Land** (*Indicate area in m²*)

i. OSHIE i. 132.72 m²

ii. ..... ii. .....

iii. ..... iii. .....

iv. ..... iv. .....

(c) **Creek/Creek lets** ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) **Swamp** ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) **River** ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) **Shoreline/water** ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☑ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☑ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation NAOC SHOULD INTENSIFY SURVEILLANCE ALONG FACILITY

12. Time Investigation ended.....