

2021/LOR/012



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: N.A.O.C.

2. Type of Complaint/Incident:

- ☒ Oil Pollution    ☐ Fire/Explosion    ☐ Drilling Mud/Chemical Pollution  
☐ Others (Specify) .....

3. Incident Details

- i. Date of Incident: 20/02/2021    ii. Date first reported: 20/02/2021  
iii. Date of first investigation: 20/02/2021  
iv. Date of follow-up investigation: .....  
v. Time investigation started: .....  
vi. Estimated quantity spilled: 0.08 barrel

4. Site Details

- i. Site/Location: BBEGORO ST. HEADLINE AT TMOKU  
ii. Position of Spill/Leak: N 05° 21' 51.2" E 006° 39' 42.2"  
iii. Spill area  
☒ Land    ☐ Swamp    ☐ Freshwater    ☐ Mangrove    ☐ Coastline  
☐ Near shore    ☐ Offshore    ☐ Others (Specify) .....  
iv. Structural Controls in Place  
☐ Boom    ☐ Trenches    ☐ Bund Wall    ☐ Sorbents    ☐ Others (Specify) N/A

5. Circumstances Around Spill Point

- i. Visual observation of Hole Position  
☒ 12 O'Clock    ☒ 10 O'Clock    ☐ 2 O'Clock    ☐ 3 O'Clock  
☐ 4 O'Clock    ☐ 5 O'Clock    ☐ 6 O'Clock
- ii. Type of Oil Contaminant  
☒ Crude Oil    ☐ Condensate    ☐ Chemicals    ☐ Refined Products  
☐ Others (Specify) .....
- iii. Facility  
☐ Pipeline    ☒ Flow Line    ☐ Wellhead    ☐ Manifold    ☐ Flow Station    ☐ Rig  
☐ Storage Tank    ☐ Compressor Plant  
☐ Others (Specify) .....
- iv. Cause of Spill  
☐ Corrosion    ☐ Equipment Failure    ☒ Third Party Interference    ☐ Accident  
☐ Operational Error    ☐ Others (Specify) .....
- v. Visible Sign of Third Party Interference  
☒ Hacksaw Marks    ☐ Drilled Holes    ☐ Blasting    ☐ Theft    ☐ Acid  
☐ Others (Specify) .....

## 6. Impact of Incident

### i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☐ Surface water  
☐ Venerable Objects ☐ Others (Specify) .....

### ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes  
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify) ....

### iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

## 7. Extent of Impact

(a) Community (Indicate name)

(b) Land (Indicate area in m<sup>2</sup>)

- i. OMOKU ..... i. 28.41 m<sup>2</sup> .....  
ii. .... ii. ....  
iii. .... iii. ....  
iv. .... iv. ....

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

(d) Swamp

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

(e) River

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

8. Photograph/Map/Chart Ref.

☒ Still photographs    ☐ Video coverage    ☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot    ☐ Boat    ☐ Aircraft

11. Remarks/Recommendation..... *NAOC should intensify surveillance along the facilities*

12. Time Investigation ended.....

13. Name and Signature of Participants

❖ NOSDRA / *[Signature]*