



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: ERO TOW E&P

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)

3. Incident Details

- i. Date of Incident: 06/10/2021 ii. Date first reported: 06/10/2021
iii. Date of first investigation: 11-10-2021
iv. Date of follow-up investigation:
v. Time investigation started: 8am
vi. Estimated quantity spilled: 5 Litres

4. Site Details

- i. Site/Location: CAWTHORNE CHANNEL 3 WELL 41S ROW @ SANDSAND
ii. Position of Spill/Leak: N 60 716.08° E 501851.28°

iii. Spill area

- ☐ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☒ Coastline
☒ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify) NIL

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 0'Clock ☒ 10 0'Clock ☒ 2 0'Clock ☒ 3 0'Clock
☒ 4 0'Clock ☒ 5 0'Clock ☒ 9 0'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)

iii. Facility

- ☐ Pipeline ☒ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify) Line

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (Specify) Puncture

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify) Shoreline

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify) Stained debris

iii. Delineation of Impacted area

- ☒ Within Company's facility/KOW ☒ Outside Company's facility/KOW

7. Extent of Impact

(a) Community (Indicate name)

i. SAND SAND

ii.

iii.

iv.

(b) Land (Indicate area in m²)

i. 100 m²

ii.

iii.

iv.

(c) Creek/Creek lets

☒ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>/</u>	<u>/</u>	<u>/</u>	<u>/</u>

(d) Swamp

☒ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>/</u>	<u>/</u>	<u>/</u>	<u>/</u>

(e) River

☒ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>/</u>	<u>/</u>	<u>/</u>	<u>/</u>

(f) Shoreline/water

☒ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>SAND SAND</u>	<u>/</u>		

min 200

8. Photograph/Map/Chart Ref.

- ☒ Still photographs ☒ Video coverage ☐ Mapping

9. Samples taken.....

10. Investigation carried out by

- ☐ Foot ☒ Boat ☐ Aircraft

11. Remarks/Recommendation..... Clean-up impacted debris on beachfront and ensure immediate repairs of affected pipeline to prevent further interference.

12. Time Investigation ended.....

13. Name and Signature of Participants

- ❖ NOSDRA
1. Oduagide, A. E. ~~Signature~~ 11/10/2021
2.
3.