

FILE: 3043922



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: S P D C

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify) 5

3. Incident Details

- i. Date of Incident: 08-10-2021 ii. Date first reported: 09-10-2021
iii. Date of first investigation: 10-10-2021
iv. Date of follow-up investigation: 28-10-2021
v. Time investigation started: 12:35 HRS
vi. Estimated quantity spilled: 125 BBLs AREA OF IMPACT = 0.56 Ha

4. Site Details

- i. Site/Location: 11th OKORODIA - RUMUWUKE PIPELINE @ ITHOWO COMMUNITY, ANIBARA LGA
ii. Position of Spill/Leak: N.S. 000856 AG. 662345

iii. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify) P.T.

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify) SABOTAGE

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☒ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid

6. Impact of Incident

i Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☒ Surface water
☐ Venerable Objects ☐ Others (specify)

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☒ Withering of vegetation ☐ Others

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

- i. 16th Row 50
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... *N/A*

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation. *SPOC should be carried out up and*

of the incident point immediately. Also clearance

of the water area should be carried out as soon
as possible. And work on site will only start in the morning.

12. Time Investigation ended... *13:25 hrs*