

APPENDIX I

SOME PHOTOGRAPHS TAKEN DURING THE JOINT INVESTIGATION VISIT (JIV)




Fig A: Suspected Incident Area on arrival of JIT



Fig B: Suspected Incident Facility shortly after excavation



Fig C: Incident facility



Fig D: Backfill