

PHOTOGRAPHS TAKEN DURING JIV



Fig A: Incident Point.



Fig B: picture taken after Patching.



Fig C: picture taken after first wrap.



Fig D: picture taken after wrapped.