

**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

*Note: This JIV Form is to be completed and signed by all participating parties in the field*

- 1. Company:** NIGERIAN AGIP OIL COMPANY LIMITED
- 2. Type of Complaint/Incident:**
- ☒ Oil Pollution    ☒ Fire/Explosion    ☒ Drilling Mud/Chemical Pollution  
☒ Others (Specify) GASEOUS EMISSION
- 3. Incident Details**
- i. Date of Incident: 15 / 04 / 2018 ii. Date first reported: 15 / 04 / 2018  
iii. Date of first investigation: 24 / 04 / 2018 iv. Spill Incident No: 2018/LAR/GLI/036  
v. Date of follow-up investigation: .....  
vi. Time investigation started: 13:04 HRS  
vii. Estimated quantity spilled(bbls): NIL viii. Quantity Recovered: NIL
- 4. Site Details**
- i. Site/Location: 6" TUOMO-OGBANBIRI DELIVERY GAS LINE  
ii. State: BAYELSA iii. L.G.A.: AKKEREMO  
iv. Spill Co-Ordinates: N(m) 4° 57' 06"  
E(m) 5° 56' 12"  
v. Spill area  
☒ Land    ☒ Swamp    ☒ Freshwater    ☒ Mangrove    ☒ Coastline  
☒ Near shore    ☒ Offshore    ☐ Others (specify) N/A  
iv. Structural Controls in Place  
☒ Boom    ☒ Trenches    ☒ Bund wall    ☒ Sorbents    ☐ Others (specify) N/A
- 5. Circumstances Around Spill Point**
- i. Visual observation of Hole Position  
☐ 12 O' Clock    ☒ 10 O' Clock    ☒ 2 O' Clock    ☐ 3 O' Clock  
☐ 4 O' Clock    ☐ 5 O' Clock    ☐ 6 O' Clock
- ii. Type of Oil contaminant  
☒ Crude Oil    ☒ Condensate    ☒ Chemicals    ☒ Refined Products  
☐ Others (specify) N/A
- iii. Facility  
☒ Pipeline    ☒ Flow line    ☒ Wellhead    ☒ Manifold    ☒ Flow Station    ☒ Rig  
☒ Storage Tank    ☒ Compressor Plant    ☒ Others (specify) .....
- iv. Cause of Spill  
☒ Corrosion    ☒ Equipment Failure    ☒ Third Party Interference    ☒ Accident  
☒ Operational Error    ☒ Others (specify) .....
- v. Visible Sign of Third Party Interference  
☒ Hacksaw Marks    ☒ Drilled Holes    ☒ Blasting    ☒ Theft    ☒ Acid  
☒ Others (specify) .....



## 6. Impact of Incident

### i Properties impacted by the incident

☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water  
☒ Venerable Objects ☐ Others (specify)..... N/A

### ii. Nature of impact

☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes  
☒ Dead floating crabs ☒ Withering of vegetation ☐ Others..... N/A

### iii. Delineation of impacted area

☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

## 7. Type of properties/ structures, if any, found outside the right-of-way

☒ Crops ☒ Fish Farm/ Pond ☒ Fishing Net ☒ Makeshift  
☒ Permanent ☐ Others ..... N/A

## 8. Extent of Impact

### a) Community (indicate name)

i. ....  
 ii. ....  
 iii. ....  
 iv. ....

### b) Land (indicate area in m<sup>2</sup>)

i. ....  
 ii. ....  
 iii. ....  
 iv. ....

### b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

| NAME  | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|-------|--------------------|-----------------|----------------|
| ..... | .....              | .....           | .....          |
| ..... | .....              | .....           | .....          |
| ..... | .....              | .....           | .....          |

### c) Swamp

☐ Tidal

☐ Non-tidal

| NAME  | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|-------|--------------------|-----------------|----------------|
| ..... | .....              | .....           | .....          |
| ..... | .....              | .....           | .....          |
| ..... | .....              | .....           | .....          |

### d) River

☐ Tidal

☐ Non-tidal

| NAME  | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|-------|--------------------|-----------------|----------------|
| ..... | .....              | .....           | .....          |
| ..... | .....              | .....           | .....          |
| ..... | .....              | .....           | .....          |

### e) Shoreline/water

| NAME  | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|-------|--------------------|-----------------|----------------|
| ..... | .....              | .....           | .....          |
| ..... | .....              | .....           | .....          |
| ..... | .....              | .....           | .....          |

9. Photograph/Map/Chart Ref.

☒ Still photographs    ☐ Video coverage    ☐ Mapping

10. Samples taken..... N/A

11. Investigation carried out by

☐ Foot    ☒ Boat    ☐ Aircraft

12. Remarks/Recommendation..... ALL AREAS OF THE COMPANIES  
RIGHT OF WAY SHOULD BE SERIOUSLY MONITORED

13. Time investigation ended..... 13:39 HRS