

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken.....NIL.....

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation.....The exercise was successful

① Provide another source of drinking water to the affected persons. ② Cleanup/remediate the impacted ground water as a matter of urgency

12. Time investigation ended.....

13. Name and Signature of Participants

12 50 hrs

❖ NOSDRA