




# NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

## JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY
2. Type of Complaint/Incident:  
☒ Oil Pollution    ☒ Fire/Explosion    ☒ Drilling Mud/Chemical Pollution  
☒ Others (Specify).....
3. Incident Details  
i. Date of Incident: 29/07/2021 ii. Date first reported: 29/07/2021  
iii. Date of first investigation: 30/07/2021 iv. Spill Incident No: 2021/SAR/047  
v. Date of follow-up investigation: 31/07/2021  
vi. Time investigation started: 13:03 HRS  
vii. Estimated quantity spilled(bbls): 25 viii. Quantity Recovered: 2 bbls
4. Site Details  
i. Site/Location: 18" OBARA/BRASS PIPELINE RISER AT TEREKE  
ii. State: BAYELSA iii. L.G.A: NEMBE  
iv. Spill Co-Ordinates: N(m) 04° 34' 37.8"  
E(m) 006° 16' 34.8"  
v. Spill area  
☒ Land    ☒ Swamp    ☒ Freshwater    ☒ Mangrove    ☒ Coastline  
☒ Near shore    ☐ Offshore    ☒ Others (specify).....  
vi. Structural Controls in Place  
☒ Boom    ☒ Trenches    ☒ Bund wall    ☒ Sorbents    ☒ Others (specify).....
5. Circumstances Around Spill Point  
i. Visual observation of Hole Position  
☒ 12 O' Clock    ☒ 10 O' Clock    ☒ 2 O' Clock    ☒ 3 O' Clock  
☒ 4 O' Clock    ☒ 5 O' Clock    ☒ 6 O' Clock    ☒ 9 O' C LOCK  
ii. Type of Oil contaminant  
☒ Crude Oil    ☒ Condensate    ☒ Chemicals    ☒ Refined Products  
☒ Others (specify) .....
- iii. Facility  
☒ Pipeline    ☒ Flow line    ☒ Wellhead    ☒ Manifold    ☒ Flow Station    ☒ Rig  
☒ Storage Tank    ☒ Compressor Plant    ☒ Others (specify).....
- iv. Cause of Spill  
☒ Corrosion    ☒ Equipment Failure    ☒ Third Party Interference    ☒ Accident  
☒ Operational Error    ☒ Others (specify).....
- v. Visible Sign of Third Party Interference  
☒ Hacksaw Marks    ☒ Drilled Holes    ☒ Blasting    ☒ Theft    ☒ Acid  
☒ Others (specify).....



## 6. Impact of Incident

### i Properties impacted by the incident

- ☒ Farmland  
 ☒ Fish Pond  
 ☒ Vegetation  
 ☒ Fishing Net  
 ☒ Surface water  
☒ Venerable Objects  
 ☒ Others (specify).....

### ii. Nature of impact

- ☒ Oil stained vegetation  
 ☒ Oil stained fishing nets  
 ☒ Dead floating fishes  
☒ Dead floating crabs  
 ☒ Withering of vegetation  
 ☒ Others.....

### iii. Delineation of impacted area

- ☒ Within Company's facility/ROW  
 ☒ Outside Company's facility/ROW

## 7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops  
 ☐ Fish Farm/ Pond  
 ☐ Fishing Net  
 ☐ Makeshift  
☐ Permanent  
☐ Others .....

## 8. Extent of Impact

### a) Community (indicate name)

- i. TEREKE  
 ii. ....  
 iii. ....  
 iv. ....

### b) Land (indicate area in m<sup>2</sup>)

- i. 141,598.223  
 ii. ....  
 iii. ....  
 iv. ....

### b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    | N/A             |                |

### c) Swamp

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    | N/A             |                |

### d) River

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    | N/A             |                |

### e) Shoreline/water

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    | N/A             |                |

9. Photograph/Map/Chart Ref.

☒ Still photographs    ☒ Video coverage    ☒ Mapping

10. Samples taken..... N/A .....

11. Investigation carried out by

☒ Foot    ☒ Boat    ☒ Aircraft

12. Remarks/Recommendation..... NAOC SHOULD CLEAN UP THE  
IMPACTED AREA IMMEDIATELY .....

13. Time investigation ended..... 06:51 PM .....