



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY [NAOC]

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify).....

3. Incident Details

- i. Date of Incident: 06/09/20 ii. Date first reported: 06/09/20
iii. Date of first investigation: 09/09/20 iv. Spill Incident No: 2020/SAR/059
v. Date of follow-up investigation: 12/09/20
vi. Time investigation started: 14:56 HRS
vii. Estimated quantity spilled (bbls): 50 viii. Quantity Recovered: IN PROGRESS

4. Site Details

- i. Site/Location: 24" OGODA/BRASS PIPELINE AT KALABILEMA
ii. State: BAYELSA iii. L.G.A.: BRASS
iv. Spill Co-Ordinates: N(m): 04° 29' 08.1"
E(m): 006° 21' 33.4"

v. Spill area

- ☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (specify).....

vi. Structural Controls in Place

- ☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify).....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock

ii. Type of Oil contaminant

- ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (specify).....

iii. Facility

- ☒ Pipeline ☒ Flow line ☒ Wellhead ☒ manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant ☒ Others (specify).....

iv. Cause of Spill

- ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (specify).....

v. Visible Sign of Third Party Interference

- ☒ Bucklaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (specify) VALVE INSTALLATION



6. Impact of Incident

i Properties impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
 ☒ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
☒ Dead floating crabs
 ☒ Withering of vegetation
 ☒ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW
 ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops
 ☒ Fish Farm/ Pond
 ☒ Fishing Net
 ☒ Makeshift
☒ Permanent
☒ Others

8. Extent of Impact

a) Community (indicate name)

- i.
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i. 31,200
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
		N/A	

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
		N/A	

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
		N/A	

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
		N/A	

9. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

10. Samples taken..... N/A

11. Investigation carried out by

☒ Foot ☒ Boat ☐ Aircraft

12. Remarks/Recommendation. NAOC SHOULD CLEAN UP THE IMPACTED AREA IMMEDIATELY.

13. Time investigation ended 16:20 HRS